

BIOMAR

North Shore Road

Grangemouth

29/04/2025

FIELD BIOLOGY REPORT No: 7

Field Biologist: Chris Gahagan

General	<p>A Field Biologist inspection of premises revealed no fresh evidence of rodent activity on site.</p> <p>The following points were noted for your attention.</p>
----------------	---

1. MAIN OFFICE			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	


2. LAB/OFFICE BLOCK			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

3. MODULAR BUILDINGS			
Observations	no problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

4. CONTROL ROOM			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

5. PANEL ROOMS			
Observations	No problems found intact at this time.		
Photographs			
Recommendations			
Action By		Date Completed	


6. PRODUCTION AREAS			
Observations	6.1 Fire door lying partially open.		


Photographs			
Recommendations	Doors should be closed when not in use to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	


7. WAREHOUSE NO. 1			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	


8. ENGINEERING			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

9. WAREHOUSE NO 2	
Observations	9.1 Old mouse droppings present in several areas around wall floor junctions.

Photographs			
Recommendations	Old droppings should be removed to allow quicker identification of fresh pest activity.		
Action By	CLIENT	Date Completed	


10. INTERNAL SILOS			
Observations	10.1 Old mouse droppings and damage noted throughout.		
Photographs			
Recommendations	Historic rodent evidence should be cleaned away to allow rapid identification of fresh activity.		
Action By	CLIENT	Date Completed	
Observations	10.2 Gap noted at wall/floor junctions.		


Photographs			
Recommendations	Gaps should be sealed to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	


11. BOILER HOUSES			
Observations	11.1 Gap noted at base of roller door of boiler room 2.		
Photographs			
Recommendations	Proofing strip could be installed to reduce risk of allowing pest ingress.		
Action By	CLIENT	Date Completed	

12. EXTERNAL SILOS			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	



13. WAREHOUSE A- E			
---------------------------	--	--	--

Observations	13.1 Gap noted at base of roller shutter door of A warehouse.		
Photographs			
Recommendations	Proofing strip could be installed to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	
Observations	13.2 Gaps noted at bottom of roller door of B warehouse.		
Photographs			
Recommendations	These gaps should be proofed to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	
Observations	13.3 Strip curtains noted to have been removed from roller doors.		


Photographs			
Recommendations	Consideration should be made to installing new curtains as this would reduce the risk of birds gaining access to warehouse.		
Action By	CLIENT	Date Completed	

14. WAREHOUSE F			
Observations	14.1 Netting damaged at external canopy at rear of warehouse.		
Photographs			
Recommendations	Repairs should be carried out to exclude birds from canopy.		
Action By	CLIENT	Date Completed	

15. SHEDS R1-R3	
Observations	15.1 Impact damage noted to cladding and brickwork around door frame of shed R1.

Photographs			
Recommendations	Repairs required to ensure pests cannot gain access to shed via gaps exposed by damage.		
Action By	CLIENT	Date Completed	
Observations	15.2 Gap present at the bottom corner of roller door of shed R2		
Photographs			
Recommendations	Gaps should be sealed to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	

16. EXTERNAL AREAS	
Observations	16.1 as stated above, damaged netting noted at warehouse F canopy.

Photographs			
Recommendations	Repairs required to exclude birds from area.		
Action By	CLIENT	Date Completed	