

**BIOMAR**

North Shore Road

Grangemouth

**30/01/2025**

## **FIELD BIOLOGY REPORT No: 6**

**Field Biologist: Chris Gahagan**

<b>General</b>	A Field Biologist inspection of premises revealed no fresh evidence of rodent activity on site.  The following points were noted for your attention.		
----------------	--	--	--

<b>1. MAIN OFFICE</b>			
<b>Observations</b>	No problems found at time of inspection.		
<b>Photographs</b>			
<b>Recommendations</b>			
<b>Action By</b>		<b>Date Completed</b>	


<b>2. LAB/OFFICE BLOCK</b>			
<b>Observations</b>	No problems found at time of inspection.		
<b>Photographs</b>			
<b>Recommendations</b>			
<b>Action By</b>		<b>Date Completed</b>	


<b>3. MODULAR BUILDINGS</b>			
<b>Observations</b>	no problems found at time of inspection.		
<b>Photographs</b>			
<b>Recommendations</b>			
<b>Action By</b>		<b>Date Completed</b>	

<b>4. CONTROL ROOM</b>			
<b>Observations</b>	No problems found at time of inspection.		
<b>Photographs</b>			
<b>Recommendations</b>			
<b>Action By</b>		<b>Date Completed</b>	


<b>5. PANEL ROOMS</b>			
<b>Observations</b>	No problems found intact at this time.		
<b>Photographs</b>			
<b>Recommendations</b>			
<b>Action By</b>		<b>Date Completed</b>	


<b>6. PRODUCTION AREAS</b>			
<b>Observations</b>	6.1 Fire door not closing fully at bait station 24.		


<b>Photographs</b>			
<b>Recommendations</b>	Repairs should be carried out to reduce risk of pest ingress.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	


<b>7. WAREHOUSE NO. 1</b>			
<b>Observations</b>	7.1 Gap noted at wall/floor junction where beam enters building at big bag discharger dust extraction panel at bait 75.		
<b>Photographs</b>			
<b>Recommendations</b>	Gap should be filled to reduce risk of pest ingress.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	

<b>8. ENGINEERING</b>			
<b>Observations</b>	No problems found at time of inspection.		
<b>Photographs</b>			
<b>Recommendations</b>			
<b>Action By</b>		<b>Date Completed</b>	

9. WAREHOUSE NO 2			
<b>Observations</b>	9.1 As per previous report, gap developing at right hand side of doorframe at D4.		
<b>Photographs</b>			
<b>Recommendations</b>	Gap should be sealed to reduce risk of pest ingress.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	

10. INTERNAL SILOS			
<b>Observations</b>	10.1 Old mouse droppings and damage noted throughout.		
<b>Photographs</b>			
<b>Recommendations</b>	Historic rodent evidence should be cleaned away to allow raid identification of fresh activity.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	
<b>Observations</b>	10.2 Gap noted at base of roller door.		

<b>Photographs</b>			
<b>Recommendations</b>	Brush strip has previously been installed but no longer adequately proofs door. A new, more robust brush strip is required.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	



11. BOILER HOUSES			
<b>Observations</b>	11.1 Roller shutter door lying open.		
<b>Photographs</b>			
<b>Recommendations</b>	Doors should be closed when not in use to reduce risk of pest ingress.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	
<b>Observations</b>	11.2 Gap noted at base of fire exit door. Proofing strip damaged.		





<b>Photographs</b>			
<b>Recommendations</b>	New proofing strip required.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	

<b>12. EXTERNAL SILOS</b>			
<b>Observations</b>	12.1 Door lying open and unattended.		
<b>Photographs</b>			
<b>Recommendations</b>	Open doors leave area vulnerable to pest ingress. Doors should be closed when not in use.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	

<b>13. WAREHOUSE A- E</b>	
<b>Observations</b>	13.1 Roller door A found to be lying open.



<b>Photographs</b>			
<b>Recommendations</b>	Doors should be closed when not in use to prevent pest ingress.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	
<b>Observations</b>	13.2 Roller door B lying open and unattended.		
<b>Photographs</b>			
<b>Recommendations</b>	Doors should be closed when not in use to prevent pest ingress.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	
<b>Observations</b>	13.3 Strip curtains noted to be damaged at roller door D. Door also lying open and unattended.		


<b>Photographs</b>			
<b>Recommendations</b>	Doors should be closed when not in use to prevent pest ingress. Damaged sections of strip curtain should be replaced.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	


<b>14. WAREHOUSE F</b>			
<b>Observations</b>	14.1 Hole noted in floor which could allow pest harbourage.		
<b>Photographs</b>			
<b>Recommendations</b>	Hole should be sealed to reduce risk of encouraging pests.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	

<b>15. SHEDS R1-R3</b>	
<b>Observations</b>	15.1 Cladding at roller door of shed R1 found to be damaged exposing a gap which could allow bird entry.



<b>Photographs</b>			
<b>Recommendations</b>	Gap should be sealed to reduce risk of pest ingress.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	
<b>Observations</b>	15.2 Pigeons (Columba livia) noted to be present in shed R2. Roller door found to be lying open.		
<b>Photographs</b>			
<b>Recommendations</b>	Doors should be closed when not in use. Pigeon removal could be carried out by Excel at an additional cost.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	
<b>Observations</b>	15.3 Gap noted in the centre of roller door of shed R3.		

<b>Photographs</b>			
<b>Recommendations</b>	New section of brush strip may be required to reduce risk of pest ingress.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	

16. EXTERNAL AREAS			
<b>Observations</b>	16.1 Cladding noted to be missing from canopy which could allow bird access to void behind netting.		
<b>Photographs</b>			
<b>Recommendations</b>	Repairs required to exclude birds from area.		
<b>Action By</b>	<b>CLIENT</b>	<b>Date Completed</b>	