

BIOMAR

North Shore Road

Grangemouth

25/07/2025

FIELD BIOLOGY REPORT No: 8

Field Biologist: Chris Gahagan

General	A Field Biologist inspection of premises revealed no evidence of current pest activity on site. The following points were noted for your attention.		
----------------	--	--	--

1. MAIN OFFICE			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

2. LAB/OFFICE BLOCK			
Observations	This area currently being renovated. No access possible at this time.		
Photographs			
Recommendations			
Action By		Date Completed	


3. MODULAR BUILDINGS			
Observations	no problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

4. CONTROL ROOM			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

5. PANEL ROOMS			
Observations	No problems found intact at this time.		
Photographs			
Recommendations			
Action By		Date Completed	



6. PRODUCTION AREAS			
Observations	6.1 Product debris noted in large quantities around machinery.		

Photographs			
Recommendations	Regular cleaning should reduce risk of product debris encouraging pest activity.		
Action By	CLIENT	Date Completed	

7. WAREHOUSE NO. 1			
Observations	7.1 Gap noted at the rear of fast action door to the left hand side.		
Photographs			
Recommendations	Gap should be filled to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	

8. ENGINEERING			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

9. WAREHOUSE NO 2			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

10. INTERNAL SILOS			
Observations	10.1 Old mouse droppings and damage noted throughout.		
Photographs			
Recommendations	Historic rodent evidence should be cleaned away to allow raid identification of fresh activity.		
Action By	CLIENT	Date Completed	
Observations	10.2 Gap noted at base of roller door.		
Photographs			
Recommendations	Brush strip present but does not adequately proof door. New brush strip required.		

Action By	CLIENT	Date Completed	
------------------	---------------	-----------------------	--


11. BOILER HOUSES

Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

12. EXTERNAL SILOS

Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	


13. WAREHOUSE A- E

Observations	13.1 Roller door B noted to have a gap at its base.		
Photographs			
Recommendations	Repairs to door required to ensure pests cannot gain access.		
Action By	CLIENT	Date Completed	

14. WAREHOUSE F

Observations	14.1 Netting at rear canopy damaged allowing birds to gain access.		
---------------------	--	--	--

Photographs			
Recommendations	Repairs to netting required to exclude birds from area.		
Action By	CLIENT	Date Completed	

15. SHEDS R1-R3			
Observations	15.1 Gaps noted between brickwork and cladding around shed R1 door.		
Photographs			
Recommendations	Gaps should be sealed to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	

16. EXTERNAL AREAS	
Observations	16.1 As above netting at rear canopy of external warehousing noted to be damaged.

Photographs			
Recommendations	Repairs required to exclude birds from area.		
Action By	CLIENT	Date Completed	