

BIOMAR
North Shore Road
Grangemouth
24/10/2025

FIELD BIOLOGY REPORT No: 9

Field Biologist: Chris Gahagan

General	<p>A Field Biologist inspection of premises revealed no evidence of current pest activity on site.</p> <p>The following points were noted for your attention.</p>		
----------------	---	--	--

1. MAIN OFFICE			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

2. LAB/OFFICE BLOCK			
Observations	2.1 Gap noted at base of entry door.		
Photographs			
Recommendations	Brush strip should be installed to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	

3. MODULAR BUILDINGS			
Observations	no problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

4. CONTROL ROOM			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

5. PANEL ROOMS			
Observations	No problems found intact at this time.		
Photographs			
Recommendations			
Action By		Date Completed	

6. PRODUCTION AREAS			
Observations	6.1 Product debris noted in large quantities around machinery.		
Photographs			
Recommendations	Regular cleaning should reduce risk of product debris encouraging pest activity.		
Action By	CLIENT	Date Completed	

7. WAREHOUSE NO. 1			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

8. ENGINEERING			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

9. WAREHOUSE NO 2			
Observations	9.1 Door D7 noted to be partially open.		

Photographs			
Recommendations	Doors should be closed when not in use to prevent pest ingress.		
Action By	CLIENT	Date Completed	

10. INTERNAL SILOS

Observations	10.1 Gap noted at base of roller door.		
Photographs			
Recommendations	Brush strip present but does not adequately proof door. New brush strip required.		
Action By	CLIENT	Date Completed	

11. BOILER HOUSES


Observations	11.2 Boiler room 2 door lying open.		
---------------------	-------------------------------------	--	--

Photographs			
Recommendations	Doors should remain closed when not in use to prevent pest ingress.		
Action By	CLIENT	Date Completed	

12. EXTERNAL SILOS			
Observations	No problems found at time of inspection.		
Photographs			
Recommendations			
Action By		Date Completed	

13. WAREHOUSE A- E			
Observations	13.1 Roller door A lying open and strip curtains damaged.		
Photographs			
Recommendations	Repairs to door required to ensure pests cannot gain access.		
Action By	CLIENT	Date Completed	

14. WAREHOUSE F			
Observations	14.1 Netting at rear canopy damaged allowing birds to gain access.		
Photographs			
Recommendations	Repairs to netting required to exclude birds from area.		
Action By	CLIENT	Date Completed	

15. SHEDS R1-R3			
Observations	15.1 Gap noted at corner of roller shutter door at door R2		
Photographs			
Recommendations	Gaps should be sealed to reduce risk of pest ingress.		
Action By	CLIENT	Date Completed	

16. EXTERNAL AREAS	
Observations	16.1 As above netting at rear canopy of external warehousing noted to be damaged.

Photographs			
Recommendations	Repairs required to exclude birds from area.		
Action By	CLIENT	Date Completed	